# Compatibility

| HES | Folger Adam | Von Duprin | Adams Rite |
|---|---|---|---|
| 1006J• | 712-75•, 732-75• | 6211•, 6211AL• | |
| 1006K•, 1006KD•, 1006KM• | 742-75• | 6210• | |
| 1006A•, 1006AD•, 1006AM• | | 6210 | |
| 1006N•, 1006ND•, 1006NM• | | | |
| 1006T•, 1006TD• | | | |
| 1006H•, 1006HD•, 1006HM• | | | |
| 1006R• | | | |
| 1006E• | | | |
| 1006Z• | | | |
| 1006J-2• | 310-2•, 310-2¾• | 6214•, 6215•, 6224•, 6226•, 6211WF• | |
| 1006H-2• | 310-3-1• | 6216• | |
| 4500• | 742-75• | | 7240•,7270• |
| 5000-501 | | 5100 | 7140, 7340 |
| 5000-501A | | 5100 | 7101, 7160, 7300 |
| 5000-502 | | 5100 | 7110, 7310 |
| 5000-503 | | | 7131 |
| 5000-504 | | | 7111 |
| 5200-501 | | 5100 | 7100, 7128, 7140, 7170, 7340 |
| 5200-501A | | 5100 | 7101, 7108, 7160, 7300 |
| 5200-502 | | 5100 | 7110, 7310 |
| 5200-503 | | | 7131 |
| 5200-504 | | | 7111, 7311 |
| 7000-701 | | | 7400 |
| 7000-702 | | | |
| 7000-783 | | | 71R1, 74R1 |
| 7000-786 | | 6113• | |
| 7000-789 | | | 71R2, 74R2 |
| 7501• | 712•, 712-75• | 6211• | 7240• |
| 7505• | 310-2•, 310-2¾• | 6214•, 6215•, 6224•, 6226•, 6211WF• | |
| 8000 | | | |
| 8300• | | | |
| 9400 | | | |
| 9500• | | | |
| 9600 | | | |

• = UL 10C fire-rated NOTE: This chart details the HES and Folger Adam products that can replace competitors products, but not necessarily the reverse.





# Compatibility

| RCI | Trine | ROFU |
|---|---|---|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| L6514 | 3478 | 1402, 1702 |
| L6504 | | |
| L6508 | 002•, 1002-2, 2002 | 1509 |
| L6507 | 2678 | |
| | | |
| S6514 | 007, 012, S012, 2007, 2009, 2012 | 1402, 1702 |
| S6504 | 012RD, S012RD | |
| S6805 | 2002, 2002WR | 1509, 1404 |
| S6507 | 2678 | 1403 |
| | | |
| 7114, 7304 | | |
| 7108, 7308 | | |
| 161 | EN-800 | |
| | | |
| | EN-850 | |
| 2114, 2314 | EN-400 | 1403 Radius |
| | | |
| | | |
| | | |
| | 4850 | |
| | | |
| 162 | 4800 | |

NOTE: This chart is offered as a convenience only. Reference should be made to the individual manufacturer's catalogs for complete data as to exact equivalents. There may be some variation in physical size, electrical characteristics and durability between strikes of different manufacturers. HES assumes no liability for differences between items compared. When compatibility is a concern, contact HES Customer Support at 800-626-7590 for application assistance. NOTE: The 105 trim adapter may be required for a neater appearance in retro-fit applications where the strike lip dimensions exceed 3-3/8".